


Report No. CG-D-82-77



FIRE ENDURANCE OF ALUMINUM AND STEEL HATCH COVERS

David Beene, Jr.
U. S. Coast Guard Research and Development Center
Avery Point, Groton, Connecticut 06340



June 1977

Final Report

Document is available to the public through the National Technical Information Service,
Springfield, Virginia 22151

Prepared for

DEPARTMENT OF TRANSPORTATION UNITED STATES COAST GUARD

Office of Research and Development Washington, D.C. 20590



NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

The United States Government does not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the object of this report.

The contents of this report reflect the views of the Coast Guard Research and Development Center, which is responsible for the facts and accuracy of data presented. This report does not constitute a standard, specification or regulation.

O. Z. Birkines

DONALD L. BIRKIMER, Ph.D., P.E.
Technical Director
U.S. Coast Guard Research and Development Center

Avery Point, Groton, Connecticut 06340

1 (19)		Techn	cal Report Docume	ntation P
Resout No.	Government Accession No.	3. Recipi	ent's Catalog No.	
Cook 00 77		0		
Scg-p-82-77		Inu		
Title and Subtitle				
FIRE ENDURANCE OF ALUMINI	UM AND STEEL HATCH CO	VERSOLL	077	
	= = =	6. Perfor	ning Organization Code	
201-10		TID for	ning Organization Repor	t No.
Maria de la companya della companya		T CC	R/DC-21/77	
David Beene, Jr.				
Streeming Organization Name and Address		10. Work	Unit No. (TRAIS)	4_1
United States Coast Guar		11 6		IPI
Research and Development	Center	II. Contr	act or Grade No	
Avery Point		12 7	of Report and Period Co	
Groton, CT 06340		— (A)	or Report and Period Co	7
Pepartment of Transportat	tion	(4)	FINAL REPOT	1
United State Coast Guard				
Office of Research and De		14. Spons	oring Agency Code	
Washington, DC 20590	- Caropinone		,	
Supplementary Notes				
Performed at the U. S. Contechnical control of the Avery Point, Groton, Cont	U.S. Coast Guard Res			
6. Abstract				
V				
The fire registeres o	f aluminum and an al			
The fire resistance of full-scale fire tests	The tests were see	natch covers	was compared i	n
WATTS at the U.S. Coas	et Guard Fire and Car	fate Test Det	deck of 1/V A	I.E.
Alabama Fire batal	st duald file and sa.			
niavalla, rive narch	covers were placed to	a 1000 squar	e foot (90 m2)	-> 50 /
fire which burned for	covers were placed in	a 1000 squar	e foot (90 m ²)	-750
fire which burned for	covers were placed in 30 minutes. Two of	a 1000 squar	e foot (90 m^2) seel and the ot	->50 /
fire which burned for three were aluminum.	covers were placed in 30 minutes. Two of Flame temperatures	n a 1000 squar these were st reached 1922	te foot (90 m^2) teel and the ote (1050%) duri	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	->50 /
fire which burned for three were aluminum.	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	-> 50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout.	-> 50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m^2) teel and the ot (1050 C) duri 17 minutes of	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout.	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been sent to the covers of	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout.	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the covers had not been seen to be a seen as a	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout.	->50 /
fire which burned for three were aluminum. the test. The alumin	covers were placed in 30 minutes. Two of Flame temperatures out that the steel covers is	n a 1000 squar these were streached 1922 on nelted within	te foot (90 m²) Leel and the ot (1050°C) duri 17 minutes of t throughout. D D C MAR 20 1978	->50 /
fire which burned for three were aluminum. the test. The alumining igniting the fire which	covers were placed in 30 minutes. Two of Flame temperatures out that the steel covers had been steel covers of the steel cover	n a 1000 squar these were si reached 1922 nelted within remained intac	te foot (90 m²) Leel and the ot (1050°C) duri 17 minutes of t throughout. D D C MAR 20 1978	->50 /
fire which burned for three were aluminum. the test. The alumining igniting the fire which is the state of th	covers were placed in 30 minutes. Two of Flame temperatures tum hatch covers had to le the steel covers to 18. Distribution of the covers to 1	these were since the service of the	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout. MAR 20 1978 B	ther ng
fire which burned for three were aluminum. the test. The alumining igniting the fire which igniting the fire which aluminum hatch covers	covers were placed in 30 minutes. Two of Flame temperatures tum hatch covers had to le the steel covers to Docum	n a 1000 square these were streached 1922 on elted within remained intactions of the square the square of the square the square of the square	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout. MAR 20 1978 B thle to the U.S	her ng
7. Key Words aluminum hatch covers hatch covers	408 730 18. Dismission Documents of the property of the prope	these were since these were since the server of the server	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout. MAR 20 1978 B The ble to the U.S. National Tech	her
fire which burned for three were aluminum. the test. The aluming igniting the fire which is the state of the	408 730 18. Dismission publications 18. Dismission publications 19. Dis	these were since these were since the service of th	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout. MAR 20 1978 B thle to the U.S	her
7. Key Words aluminum hatch covers hatch covers steel hatch covers	The steel covers were placed in 30 minutes. Two of Flame temperatures in the hatch covers had released to the steel covers in the best covers in t	these were streached 1922 on elted within remained intaction Stetement is available through the mation Service inia 22161	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout. MAR 20 1978 B The ble to the U.S. National Tech te, Springfield	her ng
7. Key Words aluminum hatch covers hatch covers	408 730 18. Dismission publications 18. Dismission publications 19. Dis	these were streached 1922 on elted within remained intaction Stetement is available through the mation Service inia 22161	te foot (90 m²) teel and the ot (1050°C) duri 17 minutes of t throughout. MAR 20 1978 B The ble to the U.S. National Tech	her ng

METRIC CONVERSION FACTORS

- Total		£ £ .	2	Ē		J. J.	ì		8	•		10 13	£ 5	37:	P.			,	1
To Find		inches	yards	wies		square inches square yards	square miles		sauces	short tons		fluid ounces	pints	gallons	cubic yards			Fahrenheit temperature	25 25 191
Sions from Metric Multiply by	LENGTH	0.04	2.5	9.0	AREA	0.16	2.5	MASS (weight)	0.035	12	VOLUME	0.03	1.06	0.26	1.3		TEMPERATURE (exact)	9.5 (then add 32)	986
Approximate Conversions from Metric Measures. When You Know Multiply by To Find		millimeters	meters	kilometers	1	square centimeters square meters	hectares (10,000 m ²)	2	grams	tonnes (1000 kg)	1	milliliters	liters	liters coho meters	cubic meters		TEMP	Celsius	of 32
Symbol		E C	E E	Ş	,	A SE	E e		σ.	ñ .		Ē		-~	m _E			O	
11111111111111111111111111111111111111	12 OS	61	181																
1		 ' '	1111		111.	- - - - -	 	' ' ' ' - -	1111		.l.,.l.	1.1.1		111			' ' ' ' ' '	1711	
 	Symbol 8	11.1,	7 5 5		11.1.	78.7g	meters m ²	e e	.i.i.i.		'l''l'		ĒĒ	 	 	_ ^E E	E.		rature
1.11.			1' '		1-1-1-		ars	e e		kilograms kg		mulliliters ml	ĒĒ	liters	liters	_ ["] E	cubic meters m ³	Celsins	temperature
1.1.	Symbol 8	1.1.	Centimeters Cm 2		AREA	78.7g	square meters square kilometers	hectares ha	grams		VOLUME		milliters al	0.24 liters i		cubic meters m ³	cubic meters m ³	Celsins	temperature
	ly by To Find Symbol		Centimeters cm 2	meters kilometers	-	Square centimeters cm ² Square meters m ²	square meters 2.6 square kilometers	hectares ha	28 grams	kilograms tonnes	VOLUME	milliliters	30 milititers ml			3.8 liters I	cubic meters m ³	(Jacobson Contraction Contract	ure subracting temperature

ACKNOWLEDGMENTS

The U. S. Coast Guard appreciates the assistance of Washington Aluminum Company, Incorporated, in providing the aluminum hatch covers for the accomplishment of this test program.

NTIS	White Section
DDC	Buff Section [7]
UNANNOUNCE	D D
JUSTIFICATIO.	N N
BY	
DISTRIB UTION,	/AVAILABILITY CODES
DISTRIBUTION	/AVAILABILITY CODESand/or_SPECIAL

TABLE OF CONTENTS

		Page
1.0	PURPOSE OF TESTING	1
2.0	BACKGROUND	1
3.0	HATCH COVER TEST PROCEDURES	1
	3.1 Description of Hatch Covers 3.2 Burn Area and Fuel 3.3 Instrumentation	4 4 4
4.0	TEST RESULTS	4
	4.1 Conditions During Fire 4.2 Effects on Aluminum Hatch Covers 4.3 Effects on Steel Hatch Covers	4 7 7
5.0	CONCLUSIONS	7
REFE	RENCES	9

LIST OF ILLUSTRATIONS

Figure		Page
1	Strength versus Temperature	2
2	Aluminum and Steel Hatch Covers	3
3	Test Coaming Dimensions and Thermocouple Placement	5
4	Flame and Hatch Cover Temperatures	6
5	Aluminum Hatch Cover Failures	8

1.0 PURPOSE OF TESTING

This test program was undertaken to investigate the fire resistance of aluminum hatch covers as compared to steel hatch covers. Two steel and three aluminum hatch covers were involved in a 30-minute fire. The temperatures and exposure times which created hatch cover failures were recorded to characterize them.

2.0 BACKGROUND

Aluminum hatch covers have been permitted on U.S. vessels since the early 1960's. Presently, Coast Guard Rules and Regulations for Tank Vessels (Title 46, CFR 32.57, and CFR 164.006) require steel or an equivalent stiffened fire-resistant metal as the primary structural material in the construction of tank vessel decks. 1,2 As stated in the SS KEYTRADER and SS BAUNE marine casualty report, 3 "aluminum covers had been permitted on U.S. vessels because it was believed that the lighter covers were less of a human safety hazard, and that if a cargo was exposed to open flames by a hatch cover failure, there would be little or no contribution to a vessel failure." If, however, aluminum covers are to be considered for approved use, they should be equivalent to steel in their fire-resistive capabilities. 4

Tank vessel casualties show that aluminum hatch covers melt and thereby compromise the deck's fire protection integrity. In the deck fire involving the SS KEYTRADER, the intense heat melted the aluminum hatch covers and allowed the fluids in tanks that were not damaged in the collision to be exposed to the fire. These additional fuel sources made the fire more difficult to extinguish and increased the extent of damage. The extensive fire damage sustained by the aluminum containers on the deck of the SS. C.V. SEA WITCH also refutes the use of aluminum as a structural component. These case histories tend to dispute the premise which permitted the use of aluminum hatch covers.

Steel is the primary construction material in tank vessels. It is also incombustible and provides high strength retention at elevated temperatures (Figure 1). Although deck fire temperatures have been measured as high as 1900°F (1038°C), steel with its higher melting point of 2606°F (1430°C) would not be expected to melt.⁵ The suitability of steel as a fire-resistive material is further upheld as case histories of tank vessel fires show that steel decks remain intact after being subjected to intense heat.³,⁶

3.0 HATCH COVER TEST PROCEDURES

The hatch cover test was conducted at the U.S. Coast Guard Fire and Safety Test Detachment in Mobile, Alabama. The testing took place on the after deck of the Tank Vessel A.E. WATTS. The 30-minute fire involved two oval steel hatch covers, two circular aluminum hatch covers, and one oval aluminum hatch cover (Figure 2). Each hatch cover was positioned on top of a 21-inch (0.53 m) high steel coaming inside the test pen.






FIGURE 1
STRENGTH VERSUS TEMPERATURE



OVAL STEEL HATCH COVER



OVAL ALUMINUM HATCH COVER



CIRCULAR ALUMINUM HATCH COVER

FIGURE 2
ALUMINUM AND STEEL HATCH COVERS

3.1 Description of Hatch Covers

The oval steel hatch covers were fabricated from low carbon steel. They were 6.25 feet x 4.25 feet x 0.5 inch $(1.91\text{m} \times 1.30\text{m} \times 0.0127\text{m})$ thick (Figure 2) with a 1 inch (2.5 cm) thick by 4 inch (10 cm) wide rubber gasket used to seal them to the coamings. The circular aluminum hatch covers were constructed of 6061 aluminum alloy in the T6 heat-treated condition. They were 4 feet (1.22 m) in diameter by 0.5 inch (1.25 cm) thick while the oval aluminum cover had the same dimensions as the steel hatch covers. All of the covers had a 1 inch (2.5 cm) thick by 4 inch (10 cm) wide rubber gasket to seal them to the coamings.

3.2 Burn Area and Fuel

A series of steel coamings, 21 inches (0.53 m) high, were constructed on the main deck of A.E. WATTS to form a shallow burn pen. The pen was 33.3 feet (10.15 m) long by 30 feet (9.14 m) wide, giving an area of 1000 square feet (90 m^2) (Figure 3).

Thirty-one hundred gallons (11,780 1) of No. 2 marine diesel fuel were floated on several inches of water inside the pen. The water removed the effect of the ship's camber, and allowed the fuel to cover the entire test pen except for existing tank tops and obstacles. It also reduced the fire's effect on the main deck thus creating safer test conditions.

3.3 Instrumentation

Type K Inconel sheathed thermocouples were embedded 0.125 inch (0.3125 cm) into each hatch cover to measure the cover's temperature (Figure 3). Three additional thermocouples were positioned on top of the pen coamings (Figure 3) and extended 8 inches (20 cm) into the flame area. This permitted a flame temperature comparison to the internal hatch cover temperatures. Ambient temperature, wind direction, and wind speed were also recorded. Prior to fuel ignition, all instrumentation channels were recorded for four minutes to obtain background conditions.

4.0 TEST RESULTS

4.1 Conditions During Fire

The following observations and data were recorded during the test. The ambient temperature was 76°F (24°C). Wind direction was northwest to southeast at an average speed of 5 miles per hour (8 km/hr). Two minutes after ignition, the test pen was totally involved in flames. It continued to burn for a 30-minutes period. Five mile per hour (8 km/hr) winds created openings in the flames and permitted observations of the hatch covers. Flame temperatures were recorded up to 1922°F (1050°C) and were high enough to melt the brass handles on the tank inspection covers inside the test pen.

The hatch cover thermocouples indicated a similar temperature rise for each cover (Figure 4). This rise varied only slightly between thermocouples on








FIGURE 3
TEST COAMING DIMENSIONS AND THERMOCOUPLE PLACEMENT

THERMOCOUPLES LOCATED ON TEST PEN COAMING











FLAME AND HATCH COVER TEMPERATURES

2





any one hatch. The variation was more pronounced between hatch covers. Hatch Cover D stands out because its overall temperature curve is lower than the others. This can be attributed to its unique positioning and its closeness to the fire pen edge. Its positioning was such that the northwest to southeast wind was blowing flames away from the cover throughout the test.

Comparing the time temperature curves of the hatch covers, we observe that a temperature plateau is achieved at approximately 8 minutes after fuel ignition, but this plateau is different for each cover (Figure 4). Wind conditions, flame exposure, and cover positioning could create the variation in the temperature plateaus.

4.2 Effects on Aluminum Hatch Covers

Ten minutes after ignition, the circular aluminum hatch covers had changed shape from convex to concave. They had melted within 17 minutes of ignition, but the exact time of melting could not be determined because observations had to be made through openings in the flames. At the 17-minute point, the flame temperatures had reached 1832°F (1000°C). By then, the oval aluminum hatch cover had melted at its outer edges and collapsed below the water level inside its 21-inch (0.53 m) coaming. At the conclusion of the 30-minutes test, the circular aluminum covers had been reduced to melted fragments (Figure 5).

The Standard Time Temperature Curve, adopted by the Coast Guard (Title 46, CFR 32.57-5), defines the required exposures that an approved hatch cover must withstand. The melting range of aluminum is well below this time temperature curve (Figure 4) thus the covers would be expected to melt and would, of course, fail to maintain the required structural fire protection of the vessel's deck.

Aluminum has less tensile strength than steel at both low and high temperatures (Figure 1). For aluminum to match steel's strength, its thickness must be increased by a factor of 1.7.8 This equivalent strength is present only at room temperature for as aluminum is subjected to increasing temperatures, its strength decreases more rapidly than steel's.

4.3 Effects on Steel Hatch Covers

The steel hatch covers remained intact throughout the fire test. The oval rubber gaskets located beneath them were partially disintegrated.

5.0 CONCLUSIONS


- (1) Aluminum hatch covers melt and collapse when exposed to temperatures experienced in tank vessel deck fires.
- (2) Aluminum hatch covers fail to provide the required fire protection integrity for tank vessel deck construction.
- (3) When exposed to a 30-minute tank vessel deck fire, steel hatch covers rovide the required structural fire protection integrity.



OLD CIRCULAR ALUMINUM HATCH COVER (A)



OVAL ALUMINUM HATCH COVER (B)



NEW CIRCULAR ALUMINUM HATCH COVER (E)

FIGURE 5
ALUMINUM HATCH COVER FAILURES

REFERENCES

- (1) Rules and Regulations for Tank Vessels. Subchapter D (Title 46, CFR Parts 30 to 40 inclusive), CG 123.
- (2) Rules and Regulations for Tank Vessels. Subchapter Q (Title 46, CFR Parts 150 to 199 inclusive), CG 123.
- (3) National Transportation Safety Board and U.S. Coast Guard. SS KEYTRADER
 AND SS BAUNE (Norwegian); Collision in the Mississippi River. Marine
 Casualty Report, Washington, DC.
- (4) The Society of Naval Architects. Aluminum Fire Protection Guidelines. Technical Research Bulletin 2-21, July 1974.
- (5) National Fire Protection Association. Fire Protection Handbook. Thirteenth Edition, 1969.
- (6) National Transportation Safety Board and U.S. Coast Guard. SS C.V. SEA
 WITCH SS ESSO BRUSSELS (Belgium); Collision and Fire in New York Harbor.
 Marine Casualty Report, Washington, DC.
- (7) American Society for Metals. Metals Handbook. Eighth Edition, 1966.
- (8) Richards, Robert and Vorthman, Robert. <u>Full-Scale Ship's Hull Exposure</u>
 <u>Fire Tests</u>. Department of Transportation, U.S. Coast Guard, June 1976.